

Wrightington, Wigan and Leigh Teaching Hospitals

NHS Foundation Trust

Information Governance Department

Suite 9
Buckingham Row
Brick Kiln Lane
Wigan
WN1 1XX

Email: foi@wwl.nhs.uk
Web: www.wwl.nhs.uk

Ref: FOI/2025/10407

Date Received: 8th January 2025

Response Due: 5th February 2025

Date: 4th February 2025

Dear Sir/Madam

With reference to your request for information received on 8th January 2025, I can confirm in accordance with Section 1 (1) of the Freedom of Information Act 2000 that we do hold the information you have requested. A response to each part of your request is provided below.

In your request you asked:

Xray Rooms/Systems;

To include, Mammography, Dental, Fluoroscopy, Interventional and plain diagnostic;

1. How many Xray systems/rooms are installed across the Trust?

21.

2. Please list the manufacturer of the installed Xray system and in which room?

Leigh Room 1 – Siemens
Leigh Room 2 - Siemens
Leigh Room 3 – Wolverton
RAEI Room 1 – Wolverton
RAEI Room 2 – Currently under replacement
RAEI Room 3 – Wolverton
RAEI Room 4 – Agfa
RAEI Room 5 – Wolverton
RAEI Room 7 - Siemens
RAEI A&E Room 1 – Agfa
RAEI A&E Room 2 – Agfa
WTN Room 1 – Siemens
WTN Room 2 – Agfa
WTN Room 3 – Siemens
WTN Room 4 – Currently under replacement
TLC Room 1 – Wolverton

TLC Room 2 – Currently under replacement
TLC Breast – Hologic x 3
Leigh Breast – Hologic

3. What model system of Xray is installed?

Leigh Room 1 – Siemens Multax Impact C
Leigh Room 2 – Siemens Multax Impact C
Leigh Room 3 – Wolverson Kavo OP 3D
RAEI Room 1 – Wolverson Arcoma Precisioni5 (Wolverson is the service provider).
RAEI Room 2 – Currently under replacement
RAEI Room 3 – Wolverson – this is a Dental OPG X-ray – Kavo OP 3D (Wolverson is the service provider).
RAEI Room 4 – Agfa Arcoma Intuition Cs (Wolverson is the service provider) (Agfa is the CR system).
RAEI Room 5 – Opera Swing
RAEI Room 7 - Siemens Artis Zee
RAEI A&E Room 1 – Agfa DX-D600.
RAEI A&E Room 2 – Agfa DR 600.
WTN Room 1 – Siemens Luminos Lotus Max.
WTN Room 2 – Agfa Intuition
WTN Room 3 – Siemens Multax Impact C
WTN Room 4 – Currently under replacement
TLC Room 1 – Wolverson Arcoma
TLC Room 2 – Currently under replacement
TLC Breast – Hologic x 3 Hologic 3DM-STs-INTL3D (Mammography).
Leigh Breast - Hologic – the model is unknown.

4. How old is the installed Xray system?

Leigh Room 1 – 2 years old
Leigh Room 2 – 2 years old
Leigh Room 3 – 4 years old
RAEI Room 1 – 3 years old
RAEI Room 2 – Currently under replacement
RAEI Room 3 – 4 years old
RAEI Room 4 – 22 years old
RAEI Room 5 – 4 years
RAEI Room 7 – 5 years
RAEI A&E Room 1 – 11 years old
RAEI A&E Room 2 – 1 year old
WTN Room1 – 1 year
WTN Room 2 – 5 years old
WTN Room 3 – 2 years old
WTN Room 4 – Currently under replacement
TLC Room 1 – 3 years old
TLC Room 2 – Currently under replacement
TLC Breast – 4 years x 2 7 years x 1
Leigh Breast – 2 years

5. Is there a service maintenance contract in place for the installed Xray system?
Yes.

6. Who is the service provider for the maintenance contract for the installed Xray system?

Leigh Room 1 – Siemens Multax Impact C – Siemens via supply chain framework.
Leigh Room 2 – Siemens Multax Impact C - Siemens via supply chain framework

Leigh Room 3 – Wolverson Kavo OP 3D - - Wolverson Xray via supply chain framework
 RAEI Room 1 – Wolverson Arcoma Precisioni5 (Wolverson is the service provider). - Wolverson Xray via supply chain framework
 RAEI Room 2 – Currently under replacement
 RAEI Room 3 – Wolverson – this is a Dental OPG X-ray – Kavo OP 3D (Wolverson is the service provider) - Wolverson Xray via supply chain framework
 RAEI Room 4 – Agfa Arcoma Intuition Cs (Wolverson is the service provider) (Agfa is the CR system) - Wolverson Xray via supply chain framework
 RAEI Room 5 – Opera Swing - Wolverson Xray via supply chain framework
 RAEI Room 7 - Siemens Artis Zee – Siemens via supply chain framework
 RAEI A&E Room 1 – Agfa DX-D600. – AGFA Healthcare
 RAEI A&E Room 2 – Agfa DR 600. - AGFA Healthcare
 WTN Room 1 – Siemens Luminos Lotus Max.- Siemens via supply chain framework
 WTN Room 2 – Agfa Intuition - AGFA Healthcare
 WTN Room 3 – Siemens Multax Impact C - Siemens via supply chain framework
 WTN Room 4 – Currently under replacement
 TLC Room 1 – Wolverson Arcoma - Wolverson Xray via supply chain framework
 TLC Room 2 – Currently under replacement
 TLC Breast – Hologic x 3 Hologic 3DM-STs-INTL3D (Mammography). – Hologic via supply chain framework.
 Leigh Breast - Hologic – the model is unknown.

Hologic maintain the majority of the Hologic equipment however Vertec maintain the Hologic fluroscan & bone densitometer.

Mobile Xray Systems;

1. How many mobile Xray systems are installed across the Trust?

12. *The mobile machines are not located in rooms as they are used for the wards and can move around. They are normally located in corridors around the hospital.

2. Please list the manufacturer of the installed Xray system and in which room?

Leigh – Ziehm x1.
 RAEI – Wolverson x 2
 RAEI – Phillips x 2
 RAEI – GE x2
 RAEI – Schimadzu x 1
 WTN – Samsung x 1
 WTN – GE x 3

3. What model system of mobile Xray is installed?

Leigh – Ziehm - Exposcope 80.
 RAEI - Wolverson MAC32D.
 RAEI – Phillips WDR R2.
 RAEI – GE - AMX
 RAEI – Schimadzu – the model is unknown.
 WTN – Samsung GM85.
 WTN – GE – AMX 4.

4. How old is the mobile Xray system?

Leigh – 17 years old
 RAEI – Wolverson – both 5 years
 RAEI – Phillips – both 5 years
 RAEI – GE – 5 years

RAEI – Shimadzu – 18 years
WTN – Samsung 5 years
WTN - GE – 23 years old, 12 years old and 15 years old.

5. **Is there a service maintenance contract in place for the installed mobile Xray system?**
Yes.
6. **Who is the service provider for the maintenance contract for the installed mobile Xray system?**
The manufacturer or a 3rd party.

DEXA BMD;

1. **How many DEXA systems/rooms are installed across the Trust?**
1.
2. **Please list the manufacturer of the installed Xray system and in which room?**
Hologic.
3. **What model system of DEXA is installed?**
Make: Hologic
Model: Hologic Horizon W.
4. **How old is the installed DEXA system?**
5 years old.
5. **Is there a service maintenance contract in place for the installed DEXA system?**
Yes.
6. **Who is the service provider for the maintenance contract for the installed DEXA system?**
Manufacturer.

If you are not entirely satisfied with this response, please do not hesitate to contact the Information Governance Department via the email address provided. If we do not hear from you within 40 days, we will assume that we have been able to accommodate your request under the Freedom of Information Act 2000.

Yours sincerely,



Tabitha Gardner
Chief Finance Officer

PLEASE NOTE:

If you are unhappy with the service you have received in relation to your request and wish to make a complaint or request a review of our decision, you should write to: Information Governance Department, Wrightington, Wigan and Leigh NHS Foundation Trust, Suite 9, Buckingham Row, Brick Kiln Lane, Wigan, WN1 1XX.

If you are not content with the outcome of your complaint, you may apply directly to the Information Commissioner for a decision at:

The Information Commissioner's Office
Wycliffe House
Water Lane
Wilmslow
Cheshire, SK9 5AF

Helpline number: 0303 123 111